FOIF RTS102 Quick Start Guide

© SAGE@CVEN, UNSW SYDNEY Dr Yincai Zhou Updated on 2019-02-28

1. Shortcut Keys

- ★ Quick settings.
- ESC Back to previous menu or mode
- SFT Shift target mode (prism, reflectless and reflectsheet) when measuring
- SFT Shift between number and alphabetics when inputting
- BS Entre electronic level mode
- BS –Backspace key for value inputting
- Func switch to next screen page

2. Acronyms

- **SD** slope distance
- HD Horizontal distance
- VD Vertical distance
- HA Horizontal angle
- VA Vertical angle

3. Configurations

Aims	Menu	Menu Path	Option	Note
Instrument Config.	Inst. Config.	CFG/2		
Auto power off	Power off	CFG/2/1	No/5/10/15/30 min	
LCD contrast level	LCD cont.	CFG/2/2	0-13 (9*)	* = default
		or {★}/3		
Reticle brightness	Ret level	CFG/2/3	0-9 (7*)	
level		or { ★ }/4		
Backlight on/off	Backlight	{ ★ }/1	YES/NO	
Laser guide on/off	Laser	{ ★ }/2	YES/NO	
Beep on/off	Кеу Веер	{ ★ }/1(P2)	0-13 (9*)	
Signal return	Signal	{ ★ }/2(P2)		Return signal
				strength
Connect to PC –	Area	MEM/USB/U	Cable reconnection required	
USB drive		Function		
Electronic bubble	{BS} key			
Observation	Meas	CFG/1		{CFG} from
settings	condition			main menu.
Distance mode	Dist mode	CFG/1/1 (P1)	SD*/HD/VD	P1 = Page 1
Dual axis level	Tilt Mode	CFG/1/2 (P1)	XonYon*/XonYoff/XoffYoff	X = v. angle
compensator				Y = h. angle

refraction	C&R crn	CFG/1/3 (P1)	.14*/.20/No	For calc. of combined correction for curvature &	
				refraction	
Vertical angle	V. Obs	CFG/1/4 (P1)	Zenith*/VA/V90		
type					
H angle type	H. Obs	CFG/1/5 (P1)	HAR*/HAL		{Func} switch to P2
Danger circle warning?	HA Buzzer	CFG/1/1 (P2)	NO*/Yes		Resection buzz when danger circle?
Coord. format	Coord. format	CFG/1/2 (P2)	N-E-Z*/E-N-Z		
Angle resolution	Ang. Reso.	CFG/1/3 (P2)	1"*/5"/10"		
Code reuse	Code eff	CFG/1/4 (P2)	Once / always		
height difference mode	VD mode	CFG/1/5 (P2)	To instrument ce station survey ma	ntre / to ark	
Distance decimal number	Mini Unit	CFG/1/1 (P3)	1 mm /0.1 mm		
Instrument	Inst. Adjust	CFG/3			
adjustment	-				
Tilt correction	Tilt Correct	CFG/2/1			Use with
					caution
Collimation	Collimation	CFG/2/2			Use with
correction	corre				caution
correction	00110				
Serial port	Comms setup	CFG/3	6 parameters		
Serial port settings	Comms setup	CFG/3	6 parameters		
Serial port settings	Comms setup 1.Baud rate 120	CFG/3 0*/2400/4800/	6 parameters 9600/19200/3840	0	
Serial port settings	Comms setup 1.Baud rate 120 2.Data bits 8bit*	CFG/3 0*/2400/4800/ ⁶ / 7 bit	6 parameters 9600/19200/3840	0	
Serial port settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev	CFG/3 0*/2400/4800/ ¹ / 7 bit en/ Odd	6 parameters 9600/19200/3840	0	
Serial port settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/	CFG/3 0*/2400/4800/ */ 7 bit en/ Odd ' 2bit	6 parameters 9600/19200/3840	0	
Serial port settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No	CFG/3 0*/2400/4800/ 6/ 7 bit ren/ Odd 7 2bit */ Yes	6 parameters 9600/19200/3840	0	
Serial port settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/	CFG/3 0*/2400/4800/ 7 bit en/ Odd 2 bit */ Yes Yes	6 parameters 9600/19200/3840	0	
Serial port settings Unit settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit	CFG/3 0*/2400/4800/ 7 bit en/ Odd 2 bit */ Yes Yes CFG/4	6 parameters 9600/19200/3840	D	
Serial port settings Unit settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F	CFG/3 0*/2400/4800/ 4/7 bit een/ Odd 2 bit */ Yes Yes CFG/4	6 parameters 9600/19200/3840	0	
Serial port settings Unit settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa*	CFG/3 0*/2400/4800/ 7 bit en/ Odd 2 bit */ Yes Yes CFG/4	6 parameters 9600/19200/3840 9600/19200/3840	0	
Serial port settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa* 3.Angle degree*	CFG/3 0*/2400/4800/ 7 bit een/ Odd 2 bit 2 bit */ Yes Yes CFG/4 / mmHg / inchH gon / mil	6 parameters 9600/19200/3840 9600/19200/3840	0	
Serial port settings Unit settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa* 3.Angle degree* 4.Dist meter*/ L	CFG/3 0*/2400/4800/ 7 bit en/ Odd 2 bit */ Yes Yes CFG/4 / mmHg / inchH gon / mil Js-feet/Int-ft	6 parameters 9600/19200/3840 9g/mbar/psi	0	
Serial port settings Unit settings Date and time	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa* 3.Angle degree* 4.Dist meter*/ U	CFG/3 0*/2400/4800/ 7 bit een/ Odd 2 bit */ Yes Yes CFG/4 / mmHg / inchH 7 gon / mil Js-feet/Int-ft CFG/1 (P2)	6 parameters 9600/19200/3840 Ig/mbar/psi	0	US format only
Serial port settings Unit settings Date and time Custom Key	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa* 3.Angle degree* 4.Dist meter*/ L	CFG/3 0*/2400/4800/ 7 bit en/ Odd 2bit */ Yes Yes CFG/4 / mmHg / inchl- gon / mil Js-feet/Int-ft CFG/1 (P2) CFG/2 (P2)	6 parameters 9600/19200/38400 Ig/mbar/psi	0	US format only Keep default
Serial port settings Unit settings Date and time Custom Key function settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa* 3.Angle degree* 4.Dist meter*/ U	CFG/3 0*/2400/4800/ 7 bit een/ Odd 2 bit */ Yes Yes CFG/4 / mmHg / inchH / gon / mil Js-feet/Int-ft CFG/1 (P2) CFG/2 (P2)	6 parameters 9600/19200/38400 Ig/mbar/psi	0	US format only Keep default for consistency
Serial port settings Unit settings Date and time Custom Key function settings EDM Settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa* 3.Angle degree* 4.Dist meter*/ U	CFG/3 0*/2400/4800/ 7 bit en/ Odd 2bit */ Yes Yes CFG/4 / mmHg / inchF gon / mil Js-feet/Int-ft CFG/1 (P2) CFG/2 (P2) {*} / F1 or ME	6 parameters 9600/19200/38400 Ig/mbar/psi	0	US format only Keep default for consistency
Serial port settings Unit settings Date and time Custom Key function settings EDM Settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa* 3.Angle degree* 4.Dist meter*/ L	CFG/3 0*/2400/4800/ 4/ 7 bit een/ Odd 2 2bit */ Yes Yes CFG/4 / mmHg / inchH / gon / mil Js-feet/Int-ft CFG/1 (P2) CFG/2 (P2) {*} / Fine AVG 3 /	6 parameters 9600/19200/38400 lg/mbar/psi g/mbar/psi AS/P3/F1 ' Fine "s" / Rapid "s	0 s″ / Tracking	US format only Keep default for consistency * = default
Serial port settings Unit settings Date and time Custom Key function settings EDM Settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa* 3.Angle degree* 4.Dist meter*/ U 1.Mode Fine "r" 2.Ref lector Prise	CFG/3 0*/2400/4800/ 7 bit en/ Odd 2bit */ Yes Yes CFG/4 / mmHg / inchF gon / mil Js-feet/Int-ft CFG/1 (P2) CFG/2 (P2) {* } /F1 or ME */ Fine AVG 3 / m*/ Sheet / No	6 parameters 9600/19200/38400 Ig/mbar/psi AS/P3/F1 ' Fine "s" / Rapid "s prism	0 s″ / Tracking	US format only Keep default for consistency * = default
Serial port settings Unit settings Date and time Custom Key function settings EDM Settings	Comms setup 1.Baud rate 120 2.Data bits 8bit* 3.Parity No*/ Ev 4.Stop bit 1bit*/ 5.Check sum No 1.Xon/Xoff No*/ Unit 1.Temp. °C*/ °F 2.Pressure hPa* 3.Angle degree* 4.Dist meter*/ U 1.Mode Fine "r" 2.Ref lector Prist 3.Pri. const -99~	CFG/3 0*/2400/4800/ 4/ 7 bit een/ Odd 2 2bit */ Yes Yes CFG/4 / mmHg / inchH / gon / mil Js-feet/Int-ft CFG/1 (P2) CFG/2 (P2) {*} / Fine AVG 3 / m*/ Sheet / No 99	6 parameters 9600/19200/38400 Ig/mbar/psi 5 AS/P3/F1 / Fine "s" / Rapid "s prism	0 s″ / Tracking	US format only Keep default for consistency * = default

5.Pressure 500 ~		
6.ppm -499 ~ 49		

4. Menu paths

To Do	Menu	Path	Option	Note
Set H angle to 0	OSET	MEAS/OSET(P1)	Press OSET twice	(in P1) use Func key
Set H angle to 0- 360	HSET	MEAS/HSET(P2)/1	Target H, Point #	(in P2) use Func key
Set H angle to 0- 360	HOLD	MEAS/HOLD(P2)	Rotate RTS to desired value and HOLD, Point a target, HOLD	(in P2) use Func key
Switch distance display	SHV1	MEAS/SHV1(P1)	SD VA HA HD VA HA VD VA HA	
Switch between distance and angle displays	SHV2	MEAS/SHV2(P1)	SD HD VD (SD/HD/VD) VA HA	(SD/HD/VD) is selected using SHV1 key
Measure a distance	DIST	MEAS/DIST(P1)	EDM setup in P3	Func key to P3
Measure point coord.	CORD	MEAS/CORD(P2)	Requires station & backsight setup	
Station setup	Occ. Orient.	MEAS/CORD(P2)/1/1	Pt#,Inst H, E0,N0,Z0, user,wind,temp,	Manual entry or READ from Mem
Azimuth setup	Azimuth	MEAS/CORD(P2/1/2/1	Angle DDD.MMSS	Manual entry
Backsight	Backsight	MEAS/CORD(P2)/1/2/2	Pt#,Inst H, EBS, NBS, ZBS.	Manual entry or READ from Mem
Scale Factor		MEAS/CORD(P2)/4/F4 MEM/1/1/F4	For selected job only	
Stake Out	Stake Out	MEAS/MENU(P2)/1(P1)	Height; Angle & Distance; Coord	Requires Station orientation
Area	Area	MEAS/MENU(P2)/3(P1)		
Offset	Offset	MEAS/MENU(P2)/4(P1)		
MLM	MLM	MEAS/MENU(P2)/5(P1)		
Resection	Resection	MEAS/MENU(P2)/2(P2)		
REM	REM	MEAS/MENU(P2)/1(P2)		
Point Projection	Point Projection	MEAS/MENU(P2)/3(P2)		

Line Stakeout	Line	MEAS/MENU(P2)/4(P2)				
	Stakeout					
Traverse	Traverse	MEAS/MENU	J(P2)/5(P2)			
Inverse	Inverse	MEAS/MENU	J(P2)/1(P3)			
Road Calc.	Road Calc	MEAS/MENU(P3)/5(P3)		Road calc / setout		After road
				/ road file		alignment
				managmt		
Choose Internal	Storage	MEM/4		Internal or SD		
mem or SD card	media			card		
Job management	JOB	MEM/1(P1)		JOB Selection		Caution to
				JOB Rename		delete a job.
				JOB Delete		No recovery.
				Download		
				COM Settings		
				File Copy (P2)		
Data download /	U Function	MEM/5		Using FOIF		Separate
upload					Exchange or MO	
	File Copy	MEM/1/1(P2) – to SD		to read data files		
Known data	Key Input	MEM/2/JOB#/1(P1)		P# E N H only		
manual input						
Code	Code Edit	MEM/3/1 Store max 50 co		des incl. string No		options to save
Management		numbers. No lim		it in data file cod		les during meas.

5. Measure distances only

- Setup instrument
- Sight to a target
- SFT to change to prism, reflective sheet or reflectless mode
- MEAS / DIST (P1) /use SHV2 to switch SD HD VD display.

6. Measure distances and angles

- Setup instrument
- MEAS / CORD (P2)
- 1. Occ. Orientation
- 2. Set H Angle
- 1. Azimuth, entre azimuth (e.g. 0)
- Sight to target 1, OK.
- 2. Measure, REC, OK
- Sight to target 2, select MEAS, REC, OK
- Repeat

7. View recorded data

• MEAS / REC (P3) / 5.View (P1) / display list of recorded points

8. Instrument Quick Configuration



Note:

- Ret. Lev = Reticle illumination level •
- Laser = constant laser beam
- Signal = laser reflection level



Inst. config

2.Signal

1.Key Beep :NO

:15



(1)

9. Data files in internal memory

U FUNCTION. Once connected, you'll see a USB drive with 5 folders in it.



10. Electronic level-up (sec 2.4)

Press BS key.



7)

GHI

O PR O Z O

DEF 8 MNO 5 VWX

ABC JKL 4 STU

PZ

11. Laser plummet activation

Press BS / F4

By default, the brightness is 0. It means no laser beam visible.

Use \triangleleft or \blacktriangleright to adjust laser beam brightness level.

Press F3 to go back to laser plummet mode or Electronic level-up mode.

